

High School Lead Testing Results (3/28/2025)

| Sample Sequence | Fixture ID Code (Sample Point field on lab report) | Fixture Location | First Draw Lead Result (mg/L) as shown on the laboratory report | 30-Second Flush Lead Result (mg/L) ("F" at end of sample point code is 30 second flush sample) | Corrective Action |
|-----------------|--|--|--|---|-------------------------|
| 1 | HS-PACHALL-BF | PAC hall bottle fill by rm 120 rt door | | | |
| 2 | HS-PACHALL-WC | Bubbler part of bottle fill unit | | | |
| 3 | HS-PACHALL-2-BF | PAC hall bottle fill by rm 120 lf door | Not detected | Not detected | |
| 4 | HS-PACHALL-2-WC | Bubbler part of bottle fill unit | Not detected | Not detected | |
| 5 | HS-KIT-6-KF | Kitchen single faucet #6 | Not detected | Not detected | |
| 6 | HS-KIT-5-KF | Kitchen single faucet #5 | Not detected | Not detected | |
| 7 | HS-KIT-KK | Kitchen kettle spray nozzle | 0.001 | 0.003 | |
| 8 | HS-KIT-2-KK | Kitchen kettle fill faucet #2 | 0.011 | 0.089 | Removed from Service |
| 9 | HS-KIT-3-KK | Kitchen kettle fill faucet #3 | 0.011 | 0.034 | Removed from Service |
| 10 | HS-KIT-4-KK | Kitchen kettle fill faucet #4 | 0.060 | 0.031 | Removed from Service |
| 11 | HS-KIT-4-KF | Kitchen single faucet #4 | Not detected | Not detected | |
| 12 | HS-KIT-3-KF | Kitchen single faucet #3 | 0.001 | Not detected | |
| 13 | HS-KIT-KF | Kitchen garbage disposal spray | 0.015 | 0.003 | Flush Required |
| 14 | HS-KIT-2-KF | Kitchen compartment sink faucet | 0.002 | Not detected | |
| 15 | HS-KIT-IM | Kitchen ice machine | Not detected | Not detected | |
| 16 | HS-PACHALL-3-BF | Bottle fill by auditorium RR's | Not detected | Not detected | |
| 17 | HS-PACHALL-3-WC | Bubbler part of bottle fill unit | Not detected | Not detected | |
| 18 | HS-PACHALL—4-W C | Water cooler by bottle fill unit | Not detected | Not detected | |
| 19 | HS-S114-CF | Room S114 faucet far right | Not detected | Not detected | |
| 20 | HS-S114-2-CF | S114 faucet #2 | 0.001 | Not detected | |
| 21 | HS-S114-3-CF | S114 faucet #3 | Not detected | Not detected | |
| 22 | HS-S114-4-CF | S114 faucet #4 | 0.002 | Not detected | |
| 23 | HS-S114-5-CF | S114 faucet #5 | 0.002 | Not detected | |
| 24 | HS-S114-6-CF | S114 faucet far left | Not detected | Not detected | |
| 25 | HS-S116-TL | S116 teacher lounge faucet | Not detected | Not detected | |
| 26 | HS-SHALL-WC | S hall left water cooler by S127 | Not detected | Not detected | |
| 27 | HS-SHALL-2-WC | S hall right water cooler by S127 | Not detected | Not detected | |
| 28 | HS-A114-TL | A114 teacher lounge faucet | 0.001 | Not detected | |
| 29 | HS-AHALL-BF | A hall bottle fill by A132 | Not detected | Not detected | |
| 30 | HS-AHALL-WC | Bubbler part of bottle fill unit | Not detected | Not detected | |
| 31 | HS-AHALL-2-WC | Water cooler next to bottle fill unit | Not detected | Not detected | |

| | | | | | |
|----|----------------|---------------------------------------|--------------|--------------|----------------|
| 32 | HS-A132-KF | A132 faucet | Not detected | Not detected | |
| 33 | HS-NHALL-WC | N hall left water cooler by N127 | Not detected | Not detected | |
| 34 | HS-NHALL-2-WC | N right water cooler by N127 | Not detected | Not detected | |
| 35 | HS-PE116-KF | PE116 faucet | Not detected | Not detected | |
| 36 | HS-PE116-IM | PE116 ice machine | Not detected | Not detected | |
| 37 | HS-PE116-OT | PE116 wall faucet | 0.003 | 0.001 | |
| 38 | HS-PEHALL-BF | PE hall bottle fill | Not detected | Not detected | |
| 39 | HS-PEHALL-WC | Bubbler part of bottle fill unit | Not detected | Not detected | |
| 40 | HS-PEHALL-2-WC | PE hall high water cooler by BFU | Not detected | Not detected | |
| 41 | HS-PE122-BF | PE122 bottle fill | Not detected | Not detected | |
| 42 | HS-PE122-WC | Bubbler part of bottle fill unit | Not detected | Not detected | |
| 43 | HS-PE122-2-WC | PE122 high water cooler by BFU | Not detected | Not detected | |
| 44 | HS-TCS-KF | TCS faucet | 0.006 | 0.001 | Flush Required |
| 45 | HS-TCS-DF | Tennis Concession drinking fountain | | | |
| 46 | HS-AFH-BF | Field house bottle fill | Not detected | Not detected | |
| 47 | HS-AFH-WC | Bubbler part of bottle fill unit | Not detected | Not detected | |
| 48 | HS-AFH-2-WC | Water cooler next to bottle fill unit | Not detected | Not detected | |
| 49 | HS-AFH-IM | Field house ice machine | | | |
| 50 | HS-ACON-KF | ACON (ATHLETIC CONCESSION) | 0.010 | Not detected | Flush Required |

Middle School Lead Testing Results (3/28/2025)

| Sample Sequence | Fixture ID Code (Sample Point field on lab report) | Fixture Location | First Draw Lead Result (mg/L) as shown on the laboratory report | 30-Second Flush Lead Result (mg/L) ("F" at end of sample point code is 30 second flush sample) | Corrective Action |
|-----------------|--|------------------------------|--|--|-------------------------|
| 1 | MS-PACHALL-BF | PACHALL bottle fill | Not detected | Not detected | |
| 2 | MS-PACHALL-WC | Bubbler part of bottle fill | Not detected | Not detected | |
| 3 | MS-PACHALL-2-WC | Water cooler right of BFU | | | |
| 4 | MS-CAF-WC | Cafeteria water cooler | 0.070 | 0.072 | Removed from Service |
| 5 | MS-KIT-KK | Kitchen kettle fill faucet | 0.004 | 0.008 | Removed from Service |
| 6 | MS-KIT-2-KK | Kitchen kettle fill faucet 2 | 0.005 | Not detected | |
| 7 | MS-KIT-3-KK | Kitchen kettle fill faucet 3 | | | |
| 8 | MS-KIT-KF | Kitchen wash/rinse faucet | 0.012 | 0.002 | Flush Required |
| 9 | MS-PACHALL-3-WC | Water cooler by room 201 | 0.003 | 0.005 | |
| 10 | MS-MHALL-WC | Main hall water cooler | | | |
| 11 | MS-TL-TL | Teacher lounge faucet | 0.002 | Not detected | |
| 12 | MS-1HALL-BF | Bottle fill by room 111 RR's | Not detected | Not detected | |
| 13 | MS-1HALL-WC | Bubbler part of bottle fill | Not detected | Not detected | |
| 14 | MS-1HALL-2-BF | Bottle fill by RR's by 155 | Not detected | Not detected | |
| 15 | MS-1HALL-2-WC | Bubbler part of bottle fill | Not detected | Not detected | |

Park Elementary Lead Testing Results (3/28/2025)

| Sample Sequence | Fixture ID Code (Sample Point field on lab report) | Fixture Location | First Draw Lead Result (mg/L) as shown on the laboratory report | 30-Second Flush Lead Result (mg/L) ("F" at end of sample point code is 30 second flush sample) | Corrective Action |
|-----------------|---|-----------------------------------|---|--|-------------------|
| 1 | PAR-102-NS | 102 - nurse's office faucet | 0.001 | Not detected | |
| 2 | PAR-103-TL | 103 - Staff lounge faucet | 0.001 | Not detected | |
| 3 | PAR-HALL-BF | Bottle fill by staff RR by 104 | Not detected | Not detected | |
| 4 | PAR-HALL-WC | Bubbler part of bottle fill unit | Not detected | Not detected | |
| 5 | PAR-KIT-KF | Kitchen faucet | 0.002 | Not detected | |
| 6 | PAR-KHALL-WC | Water coolr kitchen hall | Not detected | Not detected | |
| 7 | PAR-107-B | Bubbler in room 107 | 0.001 | Not detected | |
| 8 | PAR-206-B | Bubbler in room 206 | Not detected | Not detected | |
| 9 | PAR-201-B | Bubbler in 201 | Not detected | Not detected | |
| 10 | PAR-207-B | Bubbler in 207 | 0.002 | Not detected | |
| 11 | PAR-210-B | Bubbler in 210 | Not detected | Not detected | |
| 12 | PAR-HALL-2-WC | Water cooler hall by 220 | Not detected | Not detected | |
| 13 | PAR-3HALL-WC | Lf water cooler by south hall RRs | | | |
| 14 | PAR-3HALL-2-WC | Rt water cooler by south hall RRs | Not detected | Not detected | |

Norton Elementary

Lead Testing Results (3/28/2025)

| Sample Sequence | Fixture ID Code (Sample Point field on lab report) | Fixture Location | First Draw Lead Result (mg/L) as shown on the laboratory report | 30-Second Flush Lead Result (mg/L) ("F" at end of sample point code is 30 second flush sample) | Corrective Action |
|-----------------|--|----------------------------------|--|--|-------------------|
| 1 | NOR-HALL-WC | Main entrance water cooler | Not detected | Not detected | |
| 2 | NO-105-TL | 105/teacher lounge faucet | Not detected | Not detected | |
| 3 | NOR-101-NS | 101/nurse faucet | 0.003 | Not detected | |
| 4 | NOR-HALL-BF | Bottle fill by room 127 | 0.001 | Not detected | |
| 5 | NOR-HALL-2-WC | Bubbler part of bottle fill unit | Not detected | Not detected | |
| 6 | NOR-KIT-KF | Kitchen faucet | 0.006 | Not detected | Flush Required |
| 7 | NOR-HALL-3-WC | Water cooler by room 130 | Not detected | Not detected | |
| 8 | NOR-218-B | Bubbler in room 218 | 0.002 | Not detected | |
| 9 | NOR-220-B | Bubbler in room 220 | 0.002 | Not detected | |

Andrews Elementary Lead Testing Results (3/28/2025)

| Sample Sequence | Fixture ID Code (Sample Point field on lab report) | Fixture Location | First Draw Lead Result (mg/L) as shown on the laboratory report | 30-Second Flush Lead Result (mg/L) ("F" at end of sample point code is 30 second flush sample) | Corrective Action |
|-----------------|--|----------------------------------|--|---|-------------------|
| 1 | AND-2HALL-BF | Bottle fill by room 235 | Not detected | Not detected | |
| 2 | AND-2HALL-WC | Bubbler part of bottle fill unit | Not detected | Not detected | |
| 3 | AND-KIT-KF | Kitchen/235 faucet | 0.006 | 0.003 | Flush Required |
| 4 | AND-301-NS | 301 - nurse office faucet | Not detected | Not detected | |
| 5 | AND-305-TL | 305 teacher lounge faucet | Not detected | Not detected | |
| 6 | AND-211-B | Bubbler in room 211 | Not detected | Not detected | |
| 7 | AND-2HALL-2-WC | Water cooler by room 225 | Not detected | Not detected | |
| 8 | AND-207-B | Bubbler in room 207 | Not detected | Not detected | |
| 9 | AND-111-B | Bubbler in room 111 | Not detected | Not detected | |
| 10 | AND-1HALL-WC | Water cooler by room 127 | Not detected | Not detected | |
| 11 | AND-126-B | Bubbler in room 126 | Not detected | Not detected | |

Ruth Hoppin Elementary

Lead Testing Results (3/28/2025)

| Sample Sequence | Fixture ID Code (Sample Point field on lab report) | Fixture Location | First Draw Lead Result (mg/L) as shown on the laboratory report | 30-Second Flush Lead Result (mg/L) ("F" at end of sample point code is 30 second flush sample) | Corrective Action |
|-----------------|--|--|--|---|-------------------|
| 1 | RH-2HALL-WC | Water cooler hall by 211 | Not detected | Not detected | |
| 2 | RH-KIT-KF | Kitchen faucet | 0.010 | 0.002 | Flush Required |
| 3 | RH-101-NS | 101 - Health Room by MO | Not detected | Not detected | |
| 4 | RH-1HALL-BF | Bottle fill by kitchen across from RRs | Not detected | Not detected | |
| 5 | RH-1HALL-WC | Bubbler part of bottle fill unit | Not detected | Not detected | |
| 6 | RH-117-TL | 117-teacher lounge faucet | Not detected | Not detected | |
| 7 | RH-114-B | 114 - kinder room bubbler | Not detected | Not detected | |
| 8 | RH-119-B | Room 119 bubbler | 0.001 | Not detected | |
| 9 | RH-122-B | Room 122 bubbler | 0.001 | Not detected | |
| 10 | RH-121-B | Room 121 bubbler | Not detected | Not detected | |
| 11 | RH-1HALL-2-WC | Water cooler by 130 by RRs | Not detected | Not detected | |

Barrows Elementary Lead Testing Results (3/28/2025)

| Sample Sequence | Fixture ID Code (Sample Point field on lab report) | Fixture Location | First Draw Lead Result (mg/L) as shown on the laboratory report | 30-Second Flush Lead Result (mg/L) ("F" at end of sample point code is 30 second flush sample) | Corrective Action |
|-----------------|--|-------------------------------------|--|---|-------------------------|
| 1 | BAR-KIT-KF | Right kitchen faucet | 0.003 | 0.001 | |
| 2 | BAR-KIT-2-KF | Left kitchen faucet | 0.002 | 0.001 | |
| 3 | BAR-1HALL-DF | Left fountain by stairs & room 104 | 0.306 | 0.092 | Removed from Service |
| 4 | BAR-1HALL-2-DF | Right fountain by stairs & room 104 | 0.230 | 0.049 | Removed from Service |
| 5 | BAR-106-TL | Room106 teacher lounge faucet | 0.001 | Not detected | |
| 6 | BAR-1HALL-WC | Water cooler by room 108 | 0.001 | 0.004 | |
| 7 | BAR-2HALL-WC | Water cooler by restrooms | 0.008 | 0.008 | Removed from Service |
| 8 | BAR-201-CF | Faucet in room 201 | 0.054 | 0.017 | Hand Wash Only |